


opel 2009, 1.4 Essentia. Body Damages.




Location **Gauteng, Mamelodi**
<https://www.freedasz.co.za/x-25445-z>

2009 model, low mileage. Requires a trottle to be replaced. Needs work on the body, hail damage. Headlight, tail light, winscreen, bonnet, fenders. Interior in a immaculate.



opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z




opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z



opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z




opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z




opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z




opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z



opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z



opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z



opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z



opel 2009, 1.4 Essentia. Body Damages.

<https://www.freedasz.co.za/x-2544>
5-z