Mazda Astina 1.8 SE (50000 R)



Location Gauteng, Moot https://www.freeadsz.co.za/x-217353-z

Mazda Astina 1.8SE

Engine Overhauled. New Shocks,bearings,brakes,free flow fitted,dual branches.Dual new radiator with hydro cooler. Bumper bash at back, right brake light damaged as is boot.Light damage New 17' tyre,mags Papers in order / license disk is behind,but no fines. Project car Rewiring in progress will need to be completed.Everything is there already Non -running, no battery Needs new distrabuter to run / car did run nicely with loan distrabutor.

Alot of TLC will be req as price indicates, but mags an tyres probably worh more than price asked. AS

	編編																		
https://www.f 53-z	Mazda	https://www.f 53-z	Mazda	https://www.f 53-z	Mazda	https://www.f 53-z	Mazda	https://www.f 53-z	Mazda	https://www.f 53-z	Mazda	https://www.f 53-z	Mazda	https://www.f 53-z	Mazda	https://www.f 53-z	Mazda	https://www.f 53-z	Mazda
reeadsz.co.	Astina	reeadsz.co.	Astina	reeadsz.co.	Astina	reeadsz.co.	Astina	reeadsz.co.	Astina	reeadsz.co.	Astina	reeadsz.co.	Astina	reeadsz.co.	Astina	reeadsz.co.	Astina	reeadsz.co.	Astina
za/x-2	1.8	za/x-2	1.8	za/x-2	1.8	za/x-2	1.8	za/x-2	1.8	za/x-2	1.8	za/x-2	1.8	za/x-2	1.8	za/x-2	1.8	za/x-2	1.8
173	SE	173	SE	173	S E	173	SE SE	173	SE										



