

## VW kombi microbus (23000 R)



Location **Gauteng, Pretoria** https://www.freeadsz.co.za/x-220645-z

VW kombi body good has 1 bump spot. has gearbox and 2 complete engines with spare set of heads.

both engines striped have new oil pump and waterpump.

1 engine the head stuts broken of other can be assembled.

Needs engineering, rings and bearings to complete.

can send more pictures on.



	¥	kombi	microbus
	https://www. 45-z	freeadsz.co	.za/x-2206
	W	kombi	microbus
	https://www. 45-z	freeadsz.co	.za/x-2206
	WV	kombi	microbus
	https://www. 45-z	freeadsz.co.	.za/x-2206
	W	kombi	microbus
	https://www. 45-z	freeadsz.co	.za/x-2206
經濟	W	kombi	microbus
	https://www. 45-z	freeadsz.co.	.za/x-2206
	W	kombi	microbus
	https://www. 45-z	freeadsz.co.	.za/x-2206
	W	kombi	microbus
	https://www. 45-z	freeadsz.co.	.za/x-2206
	W	kombi	microbus
	https://www. 45-z	freeadsz.co	.za/x-2206
	W	kombi	microbus
	https://www. 45-z	freeadsz.co	.za/x-2206
犯	W	kombi	microbus
	https://www. 45-z	freeadsz.co.	.za/x-2206